

TEL:.....+47 67 03 00 00

E-mail:.....aim@avinor.no



**AERONAUTICAL INFORMATION
MANAGEMENT
P.O. BOX 150
NO-2061 GARDERMOEN**

**AIC
A 12/2026
30 SEP 2026**

**A 12 ENFL - Stenging av RWY på Florø lufthavn på grunn
av reasfaltering sommer 2027**

Planlagte reasfalteringsarbeider og oppgradering av visuelle hjelpemidler fører til at RWY 07/25 stenges i perioden fra natt til mandag 28 JUN 2027 frem til og med natt til mandag 26 JUL 2027.

Arbeidet omfatter blant annet reasfaltering av RWY med skuldre, TWY A, B, G og deler av F med skuldre og oppstillingsplattformene MAIN, og WEST. Det skal i tillegg utbedres banebelysning. Dette medfører at RWY ikke kan benyttes i stengeperioden. SAR HEL operasjoner kan fortsatt utføres fra oppstillingsplattform SAR.

Detaljer om stengingen vil kunngjøres i AIP SUP i 2027.

- Slutt -

**A 12 ENFL - Closure of RWY at Florø airport due to
resurfacing summer 2027**

Scheduled resurfacing work and upgrades to visual aids will result in the closure of RWY 07/25 from the night of Monday, 28 JUN 2027, until and including the night of Monday, 26 JUL 2027.

The work includes, among other things, resurfacing of the RWY with shoulders, TWY A, B, G, and parts of F with shoulders, as well as the aprons MAIN and WEST. In addition, runway lighting will be upgraded. This means that the RWY cannot be used during the closure period. SAR HEL operations can still be conducted from the apron SAR.

Details about the closure will be announced in the AIP SUP in 2027.

- End -