

Operational change

New Pushback Procedures at Oslo Airport

- *Effective from: 17 September 2026*
- *Version number: 01-2026*



1 Background

Avinor is introducing new pushback procedures at Oslo Airport effective 17 September 2026 at 05:00 local time. The change has been implemented to further develop the operational concept on the aircraft stands, reduce risks related to jet blast, and contribute to more predictable and efficient operations. The new procedures are also adapted to updated requirements for Apron Management Services (AMS) and are based on flight operational assessments, risk analyses, and input from affected stakeholders. In addition, the change is expected to reduce wear on pavements and infrastructure by limiting twisting damage during pushback operations.

The new procedures are intended to support the safe, robust, and efficient handling of air traffic at Oslo Airport.

2 Change description


Marking of the new pushback positions will begin this week as part of the preparations for the introduction of the new pushback procedures at Oslo Airport. It is important to emphasize that the new positions **must not be used before 17 September 2026 at 05:00 local time**.

Until the implementation date, the current pushback procedures and operational practices remain unchanged. All stakeholders shall therefore continue to operate in accordance with existing procedures until the new procedures formally enter into force. Questions should be directed to the Airside Management Department.

Disconnect Points 41, 40 and 30:




Northwest Disconnect Points:




New Disconnect Point 54:



Northeast Disconnect Points:



Disconnect Point 4:



2.1 FOLLOW-UP / IMPLEMENTATION

Airport Patrol will be present during the first days following implementation to provide guidance to stakeholders and to ensure that the new pushback procedures are followed in accordance with the applicable instructions.

3 Conclusion

This operational change enters into force on **17 September 2026 at 05:00 local time**.

For questions regarding this change, please contact the Airside Management department via email osl-airside@avinor.no