

TEL:.....+47 67 03 00 00

E-mail:.....aim@avinor.no



AERONAUTICAL INFORMATION
MANAGEMENT
P.O. BOX 150
NO-2061 GARDERMOEN

AIP SUP
46/2025
18 JUL 2025

**ENBR - RWY kantlys er erstattet på Bergen lufthavn,
Flesland**

Erstatter NOTAM A2794/25

RWY høyintensitets kantlys er erstattet med LED. REF AIP ENBR AD 2.14.

- Slutt -

**ENBR - RWY edge lights are replaced at Bergen airport,
Flesland**

Replaces NOTAM A2794/25

RWY high intensity edge lights are replaced with LED. REF AIP ENBR AD 2.14.

- End -