

Operational change

Release point 4 moved east

- *Valid from: 04.07.2025*
- *Valid to: UFN*
- *Version number: 02-2025*



1 Background

Due to damage in the asphalt on existing release point 4, the release point will be moved 20 meters to the east. This change will result in less rotation in the aircraft wheel. This will in turn cause less tear on the asphalt.

2 Change description


Release point 4 is moved approximately 20 M east on taxiway Lima blue. Distance to stand 181 from new release point location is 27.50 meters.

2.1 DEPENDENCY TABLES USED BY ATC

Dependency tables used by ATC is not affected by this change.

2.2 PUSH BACK

Push back will be conducted to the new location of release point 4.



3 Effective date

This operational change will take effect on **04.07.2025**.

For questions regarding this change, please contact Airside Management via email osl-airside@avinor.no