

Service report, Chlorine testing potable water for air crafts, Pier East, west & north.**00.01.1900**

Service according to work order

FV Tiltak: 7422



Chlorine testing and check of potable water supply for air crafts

Equipment number	Equipment	Gate	Chlorine test [ppm]	Water consumption to date [m3]	Comments	Date	Sign
+TD=319.039	Klordosering, vannfors. til fly Chlorine dosing, potable w.	39	0,63	15127		26.09.25	VH
+TD=319.043	Klordosering, vannfors. til fly Chlorine dosing, potable w.	43	0,59	10001		26.09.25	VH
+TD=319.047	Klordosering, vannfors. til fly Chlorine dosing, potable w.	47	0,54	9142		26.09.25	VH
+TD=319.048	Klordosering, vannfors. til fly Chlorine dosing, potable w.	48	0,67	5629		26.09.25	VH
+TD=319.044	Klordosering, vannfors. til fly Chlorine dosing, potable w.	44	0,48	16970		26.09.25	VH
+TD=319.036	Klordosering, vannfors. til fly Chlorine dosing, potable w.	36	0,32	10512		26.09.25	VH
+TD=319.024	Klordosering, vannfors. til fly Chlorine dosing, potable w.	24	0,41	5242		26.09.25	VH
+TD=319.020	Klordosering, vannfors. til fly Chlorine dosing, potable w.	20	0,67	10519		26.09.25	VH
+TD=319.016	Klordosering, vannfors. til fly Chlorine dosing, potable w.	16	0,63	24568		26.09.25	VH
+TD=319.012	Klordosering, vannfors. til fly Chlorine dosing, potable w.	12	0,41	11948		26.09.25	VH
+TD=319.013	Klordosering, vannfors. til fly Chlorine dosing, potable w.	13	0,43	9813		26.09.25	VH
+TD=319.017	Klordosering, vannfors. til fly Chlorine dosing, potable w.	17	0,45	10837		26.09.25	VH
						26.09.25	VH

Service report, Chlorine testing potable water for air crafts, Pier East, west & north.

00.01.1900

Service according to work order

FV Tiltak: 7422



Clorine testing and check of potable water supply for air crafts

Equipment number	Equipment	Gate	Chlorine test [ppm]	Water consumption to date [m3]	Comments	Date	Sign
Tank filling 16	Tank filling 16		0,54			26.09.25	VH
Visual check and testdrive of hose and motor	Check hose, motor, ball valve and cover.		OK			26.09.25	VH
Tank filling pir east	Tank filling pier east		0,53			26.09.25	VH
Visual check and testdrive of hose and motor	Check hose, motor, ball valve and cover.		OK			26.09.25	VH
						26.09.25	VH
+TH=319.001 (UNSØ)	Measurment celle		0,51	10069		26.09.25	VH
	Actual measuring		0,48			26.09.25	VH
	measurement in tank		0,53			26.09.25	VH
	Random gate	49	0,35			26.09.25	VH
						26.09.25	VH